













## DEMAG AC 80-2

Sample photo



Year model	2005
Last inspection	2018
Location	Finland
Availability	Today

Carrier		Superstructure	
	80 t		
	8x6x8		50 m
	~ 70.000 km		9,2 m - 17,6 m 0/20/40°
	16.00 x R 25		
	Mercedes OM 501 LA		
	Allison		1 pc or 2 pieces
			1 pc
			~13.000 h
			Full

*The unit was inspected in Finland and she is ready to work immediately.*