
















# Liebherr LTM 1090 4.1



Year model	2007
Last inspection	2019
Location	Finland
Availability	As agreed

Carrier		Superstructure	
	90 t		Liebherr D 924 TI E A 4
	8x8x8		50 m
	85.000 km		19 m
	16,00 x R 25		2 pcs
	Liebherr D 846 TI A 5		2 pcs
	ZF AS Tronic		14.900 h
			Full

*The unit was inspected in Finland and she is ready to work immediately.*