















Year model	1990
Last inspection	2018
Location	Finland
Availability	Today



Carrier	Superstructure
---------	----------------

	200 t		54,5 m
	12x8x8		13-22 m
	90.000 km		14-42 m
	16.00 x R25		
	Mercedes		Mercedes
			1 pc
	7800 h		150 ton - 80 ton - 12 ton
			17.500 h
			60 t

tr e pments not ced

- Webasto upper and carrier
- Telma brake
- Anemometer
- Spare wheel with rim

he eh c e s r o d nspected nd s perstr ct re s so nspected o c n n nd nd s re d to or mmed te .

erse tr nsport need 2 m nd eh c e tr nsport ton. e c n m e n o e r o th t too.